

~~SECRET~~

DPD 4302-59
1 July 1959

MEMORANDUM FOR: Chief, Materiel Branch, DPD-DD/P

SUBJECT : Elint Malfunction Report for June 1959

1. Detachment "C" reports no mission or preflight malfunctions and only routine bench check problems on the System III and the Rambo TWT amplifier.

2. Detachment "B" submitted an extensive report of minor bench check failures. Notable among these were 5 capstan and 1 take-up motor drive assemblies which indicates the defective units are being worked out of the equipment. There were malfunctions on 4 missions as follows:

8 June - Mission 1512 - System VI - cable broken at plug. Repaired.

12 June - Mission 1515 - System III - receivers locked on spurious signals due incorrect sensitivity setting. Corrected.

13 June - Mission 1516 - System VI - recorder plug not secured.

18 June - Mission 4122 - System VI - recorder plug loose.

25X1

SIGNED *1/6*

Chief,

25 YEAR RE-REVIEW

Distribution:

Orig & 1 - Addressee

1 - O-15

4 - RI

1 - Chrono

WWB/bs

~~SECRET~~